

805 MHz cavity refurbishment

NFMCC collaboration meeting

LBNL

1-09


Bob Rimmer

JLab


# 805 MHz cavity refurbishment

- Cavity was heavily arc damaged after many runs at high magnetic field
- Heavy pitting on button holder, irises (with slight “dipole” asymmetry)
- Further inspection revealed significant damage in the coupler region
- May explain why all button tests followed similar processing curve with magnetic field

# 805 Cavity “before”




# Coupler region damage





# Coupler region damage



# Coupler extension damage




# Refurbishment

- Polish out all visible iris damage
- Polish out arc marks in coupler region
- Polish out arc marks in coupler extension
- Cut inner and outer blend radii on coupler
- Ultrasonic clean and DI water rinse (HPR)
- Clean room assembly (to be done)
  - Cu and Be windows available
  - Button holder needs to be re-worked or re-made
- No electropolishing




# Iris restored by hand-working





# Key cutter used for inside blend



# Copper windows

